

“Probes_Manager_Setup.exe” software history 3.08

Here are reported only the last 3 releases, the complete release history is available on request

Ver.	Date	Applied Modifications
3.08	03/05/2024	– Probes manager.exe rel. 3.09 – LR01AMCEthTool.exe rel. 1.03
3.07	08/04/2024	– Probes manager.exe rel. 3.08 – LR01 Firmware 1.28
3.06	16/01/2024	– Probes manager.exe rel. 3.07

Probes_Manager.exe		
Ver.	Date	Applied Modifications
3.09	03/05/2024	– Implemented flat probes – Modified communication using LR01AMCEthTool.exe driver for Ethernet management – Fixed minor bugs
3.08	08/4/2024	– Minor changes in logger function – New implementation for flat probe EP-1N-09 and EP-1B-10 – Implemented the possibility to select alarm notification (Buzzer, LED, Vibration) – Implemented, for EHP-2B shaped probes, when correction in frequency is ON, the visualization of correlated units and graphic display of the standards ICNIRP 98/2020, SC6 and FCC
3.07	16/01/2024	– Minor bug fix. Fixed bug in plot mode using EP60X models

Firmware LR01		
Ver.	Date	Applied Modifications
1.19	11/12/2023	– Minor bug fixed
1.17	24/11/2023	– Minor bug fixed
1.15	29/09/2023	– Minor bug fixed – Implemented linear/quadratic weighting for EHP-2B

LR01AMCEthTool.exe		
Ver.	Date	Applied Modifications
1.03	22/04/2024	– Fixed minor bugs
1.0	27/11/2023	– First release