

“ER9000 Firmware receiver history

Here are reported only the last 3 releases, the complete release history is available on request

Firmware ER_EMIRceiver.Idr		
Ver.	Date	Applied Modifications
1.53	08/11/2023	- General improvements
1.52	23/06/2023	- Fixed time base issue in the click measures that caused the test duration to be wrongly calculated
1.51	28/04/2023	- Fixed minor issues.